

Editor's Note - Superseded by 96-12-06

TELEDYNE CONTINENTAL MOTORS:

Amendment 39-2925. Applies to all Model O-200-A, -B and -C engines.

Compliance required within the next fifty (50) hours time in service after the effective date of this A.D., unless already accomplished.

To prevent the possibility of cylinder head cracking, accomplish the following:

A. Reset magneto to engine timing to 24 degrees (+1 degree, -0 degrees) BTC on both magnetos.

B. Overstamp the engine data plate timing number with the current 24 degrees setting.

C. Make a log book entry stating that the timing change has been made in compliance with this A.D.

NOTE: TCM Service Bulletin M77-12 pertains to this subject.

This amendment becomes effective June 24, 1977.