

**47-43-02 CESSNA:** (Was Mandatory Note 13 of AD-768-5.) Applies to 120 and 140 Aircraft Serial Numbers 8001 to 8480, Inclusive.

Compliance required prior to January 1, 1948. To eliminate the possibility of confusion in the operation of the fuel selector valve, remove the embossed pointer from the selector valve handle and ascertain that the selector valve handle and ascertain that the selector valve handle is installed so that the handle indicates correctly the position of the selector valve as shown by the valve placard.

(Cessna Service Letter SLN-48 dated 08-19-47 covers this same subject)