



International Cessna 120-140 Association Supplemental Type Certificate Information

STC Number:

SA4-581

This certificate issued to:

Russell Conversions, Inc.

STC Holder's Address:

7829 Windover Way
Titusville FL 32780
United States

Description of the Type Design Change:

Installation of a Lycoming O-290-D engine and Sensenich M76AM-2 or Sensenich CS3FM4 propeller, in accordance with McKenzie Aircraft Repair Installation Instructions and Supplemental Parts List dated June 28, 1958, and McKenzie Aircraft Repair Installation Instructions and Parts List dated September 10, 1955, and McKenzie Aircraft Repair Drawing L149-0600-244, Revision 4, dated June 23, 1958, Sheets 1 and 2, or later FAA approved revisions to all of the above.

Application Date:

03/01/2002

Status:

Reissued and Amended

Responsible Office:

ACE-115A Atlanta Aircraft Certification Office
Tel: (770) 703-6035

TC Number	Make	Make
5A2	Cessna Aircraft Company	140A
A-768	Cessna Aircraft Company	120-140